



ASSEMBLY INSTRUCTIONS

1. Strip cable jacket to expose conductor wires & cable shield (if using)
2. Fold/Wrap back cable shield over cable jacket to ensure, once inserted in steps below, it will make contact with inner metal walls of (2) straight housing
3. Insert the stripped cable into (3) gland nut and (2) straight housing
4. Solder the cable discrete wires to the solder cups on (1) Male/Female Insert (strip conductor wires as needed)
5. Screw together the (2) straight housing and the (1) Male/Female Insert, ensure the folded/wrapped shield is in contact with inner metal walls of (2) straight housing. Complete assembly of components mentioned
6. Screw (3) gland nut onto (2) straight housing

For any questions contact eng@norcomp.net

RoHS COMPLIANT



THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF NorComp AND SHALL NOT BE REPRODUCED, COPIED OR USED AS THE BASIS FOR THE MANUFACTURE OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION.

DRAWN:
J. KADEL

DATE:
04/10/2025

NorComp

DO NOT SCALE FROM DRAWING

SCALE:
NTS

SHEET 1 OF 1

REV
0

DWG NO.
M12 CABLE KIT ASSEMBLY INSTRUCTIONS