


ASSEMBLY INSTRUCTIONS:

- 1. CHOOSE THE STRAIN RELIEF THAT MOST CLOSELY MATCH THE CABLE O/D AND SLIDE OVER CABLE JACKET
- 2. PREPARE CABLE ENDS, CONNECT TO CONNECTOR
- 3. IF CABLE IS SHIELDED, FOLD SHIELD AND/OR GROUND WIRE BACK OVER STRAIN RELIEF. CUT OFF ANY EXCESS WIRE SO IT DOES NOT STICK OUT OF THE HOOD
- 4. INSERT THE STRAIN RELIEF INTO THE STRAIN RELIEF RECESS AREA IN ONE HALF OF THE HOOD. IF THE CABLE IS BIGGER THAN ANY OF THE STRAIN RELIVES. THE CABLE MAY BE INSERTED WITHOUT A STRAIN RELIEF
- 5. INSERT THE JACKSCREWS INTO THE HOOD WITH THE
- 6. PLACE THE OTHER HALVE OF THE HOOD ON TOP OF THE FIRST HALF, MAKING SURE NO WIRES ARE PINCHED
- 7. HOLDING THE HOOD HALVES TOGETHER, INSERT THE MOUNTING SCREWS AND TIGHTEN THE TWO HALVES



DIE CAST

M	THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF NorComp AND SHALL NOT BE REPRODUCED, COPIED	DRAWN: C. SMITH		DATE: 03-31-06		
	OR USED AS THE BASIS FOR THE MANUFACTURE OF SALE OF APPARATUS WITHOUT WRITTEN PERMISSION.	CHECKED:		DATE:	X	
		SCALE:	SHEET	OF		REV
NorComp		N.T.S.		2	2	0
		BACKSHELL - 981 SERIES				