## (Product Notification)

Friday, December 15th, 2023

PCN# 121223

To Whom It May Concern:

Please be advised NorComp will now process the following part numbers with a locator plate. The attached drawing has been updated to show this change. Please note this will be a rolling change while we consume previous inventory of parts processed without the locator plate.

- 781-M15-113R141
- 781-M26-113R141
- 781-M44-113R141

This change will not affect the part's form, fit, or function; therefore, this does not affect parts previously purchased. Our records show that you have purchased some of these products in the last 5 years and therefore we are sending out this notification to you.

Please note, this PCN supersedes the previous PCN# 010719.

We appreciate your understanding as we strive to offer you the most current information regarding our product.

Please confirm receipt & acceptance of product change notification <u>by responding to this email</u>. If you have any questions or concerns, please feel free to contact us at <u>sales@norcomp.net</u>.

Regards,

Joshua Kadel Engineering Team Lead